How the Ehime Maru tragedy happened

Events that occurred nine miles south of Oahu on Feb. 9, according to testimony at the Navy's court of inquiry, the National Transportation Safety Board, and news reports.

Flawed sonar and visual check failures

The 16 civilians in the control room and a rushed emergency surfacing drill contributed to a flawed periscope and sonar check.

Lunch with civilian guests ran long and caused the crew to spend only 80 seconds scanning the horizon with the periscope, rather than the prescribed three minutes.

At the time of the periscope sweep, the Ehime Maru was only 2.200 feet away. Also, there was an inoperable sonar display in the control room.

Ehime

Maru

B The ascent

Ten minutes after diving, the crew conducted the main emergency ballast blow by forcing air into the ballast tanks while simultaneously forcing out water. This instantly lightened the submarine and propelled it to the surface at a speed of 35 mph.

Water is forced out of the sub's ballast tanks

A Surfacing and collision

Crew members of the Ehime Maru spotted the Greeneville's nose suddenly surfacing off the port side of their ship's stern. The submarine's rudder sliced open the ship's hull, directly under the engine room. Water flooded the ship and electrical power was lost, disabling the radio.

Impact

Ehime Maru

When the Greeneville struck the Ehime Maru, civilians on the sub remember hearing a loud bang, and then the sub shuddered. Greeneville Cmdr. Waddle then said. What the hell was that?

6 USS Greeneville halts and stabilizes

After the collision, the Greeneville stabilized on the surface. The crew knew they had hit something, due to the shudder of the sub when it hit the Ehime Maru. The crew radioed the Coast Guard for help, then turned the sub around and remained at the scene. The crew would later be criticized for not attempting to pick up survivors, but the Navy has insisted that due to the rough seas, the attempts would have only endangered more lives.

> **USS Greeneville** Normal crew: 146 enlisted, 17 officers Feb. 9, 2001 crew: 95 enlisted, 11 officers



GRAPHIC BY DAVID SWANN/ STAR BULLETIN

Greeneville 14 times heavier

Ehime Maru s hull, the 6.927-ton Greeneville collided with the 500ton vessel with enormous force.

Evidence of the collision visible on the rudder and port quarter side of

Built with case-hardened steel that is many times thicker than the Ehime Maru USS Greeneville 400 ft.

Sonar spotted ship The fire control technician had

data showing the Japanese boat was within 4.000 vards of the sub, but did not tell the commander or the officer of the deck because he says he didn't see the sonar contact. The process to analyze surface sonar contacts usually takes 10-15 minutes, and the Greeneville did it in six minutes.

Straight on Side profile

High-look periscope depth

Normal periscope depth

Line of sight

Periscope check

High waves could have

hidden the Ehime Maru

because the Greeneville

time at a periscope depth

did not spend enough

of 60 feet. and then

again at 58 feet.

8-ft. swells

If the white-painted Ehime Maru was heading toward the submarine against a light, overcast sky, it would have appeared as a small, narrow silhouette. This view is more difficult to see than a side profile.

Crucial minutes under water

At 1:06 p.m., just 37 minutes before the collision, the executive officer reminded Cmdr. Scott Waddle of the time. Waddle replied, I have it under control.



A The dive

Once the

submarine

search for

conducted its

vessels or other

objects, it began

a dive to gain

enough speed

and depth to

practice main

perform a

emergency

to 400 feet

ballast blow.

This involves a

10-minute dive

before leveling

Intact and upright

The Ehime Maru settled on the ocean floor in an upright position 2,003 feet below the surface. Based on the videotape taken by the Navy's remotely operated vehicle, the ship is intact and only 1,000 yards from where it was hit.



Ehime Maru sinks The ship sank in less than 10 minutes. Six

life rafts came to the surface. Of the 35 crewmen, 26 swam to them and were rescued by the Coast Guard.

Collision course

270°

At the time of the collision, the Ehime Maru was heading southeast at 166 degrees, while the Greeneville was heading northeast at 120 degrees at 20 knots.